

## Software History

### Warning:

This software is only for TV set with TPN1011E\_X.XXX.

Always check the current software in your TV set before you update the software. Uploading the wrong software to your TV set may cause malfunction to your TV set.

**NOTE:** Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

#### **TPN1011E\_V2.18** *(Date published: 2015-06-23)*

- Issue fix: TV reboot of DVB-C CATV provider Telekabel
- Issue fix: [Hungry] DVB-C channels packs on 120 MHz and 128 MHz mosaic effect
- Issue fix: TV is switching channels by itself in DVB-C.
- Issue fix: Teletext language group value not able to keep last status.

#### **TPN1011E\_V2.15** *(Date published: 2014-08-29)*

- Issue fix: TXT Language group setting value.

#### **TPN1011E\_V2.14** *(Date published: 2014-06-10)*

- Issue fix: [Estonia] cracking sound for ATV.
- Issue fix: Picture drops.
- Issue fix: [Austria] UPC jumping channel by itself.
- Issue fix: [Germany] DVB-C loss of all digital services after a night in standby.
- Issue fix: [Italy] channel loss.
- Issue fix: [Portugal] DVB-T reboots sporadically.
- Issue fix: TV cannot re-order in DVB-S.

#### **TPN1011E\_V2.13** *(Date published: 2014-03-18)*

- Issue fix: Character set for Cyrillic.
- Issue fix: Sync 2K13 set solution of startup reboot issue.
- Issue fix: Sync 2K13 set DVB-T Modena reboot issue when channel scan in Italy.

#### **TPN1011E\_V2.12** *(Date published: 2014-03-03)*

- Issue fix: Field reboots issue.

#### **TPN1011E\_V2.11** *(Date published: 2014-02-11)*

- Add multimedia player new feature: character set.
- Issue fix: DVB - T and DVB - C channel sorting at Slovenia.
- Issue fix: Digital channel default value at Slovenia.
- Issue fix: France simulcast
- Issue fix: DVB - T channel scan hand-up in Italy Varedo area.

#### **TPN1011E\_V2.09** *(Date published: 2013-11-11)*

- DVB-C HD channel & UPC broadcasting mosaic issue at Netherland.
- Add Ziggo icon for country Netherland.

- Remove Micro Dimming item from OSD UI.
- Polish Translation error.

**TPN1011E\_V2.02** (*Date published: 2013-08-31*)

- Initial production software for H-models.