

## Software History

**NOTE:** Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

### **TPN163E\_2.300** (*Date published: 2018-06-25*)

- TV reboot after press on EPG RC key - Slovenia.

### **TPN163E\_2.280** (*Date published: 2018-05-16*)

- DVB-S channel decryption ability lost after zapping in certain CAMs - Germany.
- Improve TV reboots when in TV turn on.
- EUM update.

### **TPN163E\_2.270** (*Date published: 2017-11-16*)

- Fixed the TV no sound issue when wake up TV from StandBy status – Demark.
- Prevention TV auto turn on.

### **TPN163E\_2.260** (*Date published: 2017-08-22*)

- Fixed the channel +/- no response.
- Fixed TV starts up by itself.
- Fixed the no signal after start up – Turkey.

### **TPN163E\_2.230** (*Date published: 2017-06-06*)

- Channel list items are losing encryption status indicator.
- Hissing sound on analog channels – Russia.
- UI Translation – Russia.

### **TPN163E\_2.210** (*Date published: 2017-04-26*)

- Fixed the free channel cannot display normal when specific CAM card insert – Germany.
- TV reboot with local DVB-C signal - Romania.

### **TPN163E\_2.190** (*Date published: 2017-02-07*)

- Fix VGA connected to 22" 24" TV cannot turn off by remote control.

### **TPN163E\_2.180** (*Date published: 2017-01-25*)

- TV switches to another regional broadcast transmitter – UK.
- Improvement – TV stability.
- Improvement in DVB-S channel installation.
- Bluetooth translation corrective – Czech/Slovak.
- Channel names are missing – Slovenia.

### **TPN163E\_2.160** (*Date published: 2016-11-07*)

- Improvement in DVB-S channel installation.
- Fix the channel missing in Croatia.

### **TPN163E\_2.120** (*Date published: 2016-09-30*)

- Improving UI content.
- Improving Slovenia translation
- Correct Astra 19.2E satellite name on loading bar.
- Fix TURKSAT 42E channel not found, if it is not in the first position.

**TPN163E\_2.090** (*Date published: 2016-08-17*)

- Improving joystick sensitivity.
- Adding rolling teletext function of UI.
- Fix the OAD update message overlap issue.

**TPN163E\_2.070** (*Date published: 2016-08-03*)

- UI/OSD message content corrective.
- UI translation corrective in RU.
- Fix the time zone of Turkey.

**TPN163E\_2.020** (*Date published: 2016-07-12*)

- Initial production software.