#### **Software History**

**NOTE:** Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

## **L12M31L\_003.010.000.001** (Date published: 2014-10-01)

Update Skypekit ver 4.6

## **L12M31L\_003.009.000.001** (Date published: 2014-05-28)

- Integrate the official Ginga AR release.
- Fixes Brazil dynamic screen resolution & font accuracy issue.
- Improve the TV's performance when using the special effects (Red card, goal, fireworks and so on) in WorldCup Ambilight App.
- Resolve Red and Yellow flag issue reported on worldcup ambilight app (IOS version)
- Resolve no audio and video after switching from Smart TV to Social TV and back to Smart TV issue.

## **L12M31L\_003.007.000.001** (Date published: 2014-04-16)

- Lounge light not able to turn off in standby mode
- World cup ambilight issues
- Security issue
- **L12M31L\_003.005.000.001** (Date published: 2014-03-26)
- Feature improvement Miracast functionality, Youtube LB ver4, 3D Netflix, Argentina Ginga solution
- CR to remove the MyRemote Recording menu item under Network settings (Specs removal EPG on the go)
- Connection to Philips Portal when in Demo mode (bug fix)
- WiFl reboot issue,
- Robotic Noise (Analog ch) on 5508 series
- Progress bar on DMR

## L12M31L\_003.004.000.001

- Netflix Dail
- Dash playback fail issue
- Port Ginga.AR solution for Argentina

## L12M31L\_003.003.000.001

- UI changes related to software upgrade wizard
- Blanking observed in 3D mode
- No flash UI displayed after offline programming
- CR to remove the MyRemote Recording menu item under Network settings
- TS13PHILTMTK00-134(200697): Videostore [TOPFUN]: Video play back failed error message is displayed
- MTK patch related to PR 146
- Robotic Noise issue reported on 5508

## L12M31L\_003.002.000.001

- 107 -- M118 Progress bar on DMR
- 148 -- MaxDome no audio issue
- Disable letter box in 3D (Black screen in 3D issue)
- xTV Ambilight patch (To resolve Ambilight + Hue issue)
- xTV Timeshift Pause key patch RF4CE sw version solution
- DNM de-couple with MJC

## L12M31L\_003.001.000.001

- Trick mode issue observed in TopFun app
- No audio issue in MPEG DASH clear content
- Improvement on the latency issue during Miracast
- Patch related to HD Natural Motion.
- Patch related to Directfb key dispatcher update
- YTLB V4
- MPEG DASH (clear content)

## L12M31L\_002.002.000.001

- MTK patch to improve blue mute issue during Miracast
- MTK patch related to PR#13
- MTK patch related to PR#117 (Missing minor channels related to MRA Watch TV)

## L12M31L\_002.001.000.001

- Miracast: Updated TV name is not automatically reflected on mobile device
- Argentina factory issue: OSD string displayed out of the dialog box at the end of Virgin Installation.
- PR#98: [Miracast][M115] Miracast connection fails.
- To sync the robotic noise solution in 2K12 to 2K13 (by setting the set MTS pilot offset detection to TRUE)
- Included the solution for WiFi reboot issue reported from Sau Paulo
- To optimize the buffer management for Miracast to resolve intermittent blue mute on TV set when data link is loss.
- New eDFUs with the entity updates

## **L12M31L\_001.020.000.000** (Date published: 2013-09-04)

• Stability improvements.

## **L12M31L\_001.017.000.001** (Date published: 2013-05-27)

- TV turns off and on by itself in [Pointer/mouse settings].
- TV turns off and on by itself when Ginga application is loaded.
- TV exits by itself from [Connect to network] during first time installation with HDMI-CEC-compliant device connected.

- OSD update for Spanish language.
- Removed the [Arrow keys/pointer] menu.

# **L12M31L\_001.014.000.001** (Date published: 2013-05-22)

• Introduction of new product ranges.

# **L12M31L\_001.009.000.001** (Date published: 2013-05-08)

• Initial production software for 5000/5500 series.

# **L12M31L\_001.008.000.001** (Date published: 2013-05-08)

Initial production software for 4500 series.