

## Software History

**NOTE:** Each release contains all solutions identified in the earlier version.

### **TPM186E\_018.005.007.001 (Date published: 2020-03-24)**

- Home/setup menu hang up/freezing issue.
- Game mode picture style setting not retained after waking up from standby issue.
- Pathe App Trailer playback freezing issue.
- Further improvement on Netflix error TVQ-PM-100 issue.
- Improvement on smart TV connection issue.
- TV switches sources unexpectedly with multiple HDMI CEC devices connected issue.

### **TPM186E\_018.004.223.001 (Date published: 2019-11-05)**

- Popping sound hear in TV speaker when switches to Dolby Digital Channels in the HDMI set top box.
- Netflix error TVQ-PM-100 issue.
- Error data handling and recover
- Danish menu translation error.

### **TPM186E\_018.004.187.001 (Date published: 2019-07-04)**

- Resolve smart TV Apps “NPO”, “TV2 play”, “NLZIET” and “Pathe” video playback issues
- Resolve Russia DVB-S tri-color CAM installation, TV lost channel list after long standby issue.
- Resolve UK FVP app not working issue.
- Resolve Miracast connection, mobile device cannot find TV network name issue.
- General Stability improvement.

### **TPM186E\_018.004.146.001 (Date published: 2019-04-11)**

- Resolve SF Anytime App video playback issue
- Resolve UK BBC Apps disappeared from home screen issue.
- Resolve the smart TV connection issue related to IPv6 DNS Query issue.
- Resolve HbbTV not working after Teletext On/off issue.
- Resolved input time lag in monitor picture style after waking up from standby issue.
- Resolve Delta volume setting not stored issue.
- Cyber security patch.

**Note:** For UK consumers, if the preinstalled BBC Apps have disappeared from the home screen before the software update, please do a re-install TV (Press setup key on RC -> All settings -> General settings -> Reinstall TV) to recover these pre-installed Apps back to the home screen.

### **TPM186E\_018.004.076.001 (Date published: 2018-12-01)**

- Resolve You Tube screen off mode wake up issue
- Resolve device portal connection issue reported in some retail outlets.
- Resolve the timeshift playback control bar display issue.
- Resolve TV occasionally switches audio to headphone without headphone connected during start up issue.

### **TPM186E\_018.004.007.031 (Date published: 2018-09-24)**

- Resolve wifi module queue block issue.
- Resolve UK FVP issues.

- Add Russia NTV+ and Tricolor Satellite package installation.
- Resolve HbbTV issues
- General stability improvement.

**TPM186E\_018.002.211.001** (Date published: 2018-07-18)

- Resolve subtitle off issue in UPC Switzerland.
- Resolve DVB-S channel lost issue in Switzerland.
- Reduce the scanning time of Telemach DVB-C channel installation in Slovenia.
- General Stability improvement
- Network connectivity improvement
- Resolve UI translation issues.
- Remove unused data in buffer memory

**TPM186E\_018.002.108.041** (Date published: 2018-05-18)

- modified panel parameter to solve 49PUS6803/12 vertical line noise issue.

**TPM186E\_018.002.108.011** (Date published: 2018-04-24)

- Support UK FVP.
- Support Albanian Language
- General Stability improvement
- eUM (electronic User Manual) update
- Resolve UI translation issues.

**TPM186E\_018.002.023.031** (Date published: 2018-03-22)

- modified panel parameter to solve 55PUS6503/12 picture flicker issue.

**TPM186E\_018.002.023.021** (Date published: 2018-02-23)

- Initial production software.