

## Software history – Philips 2K19 65x4/67x4/6804/6814/OLED754 ranges

### TPM196E\_091.004.027.011– Date: 2021/05/09

- Fix for no picture with some specific set top boxes

### TPM196E\_091.004.027.001– Date: 2021/04/09

- Changes on preinstalled apps and search engine in internet browser when Russia is chosen as installation country
- Improvements for live stream playback in apps
- Improvements on Ambilight + Hue
- Improvements for no reaction on RC buttons when hbbTV is enabled
- Many more minor improvements
- General system stability improvements

### TPM196E\_091.003.255.001– Date: 2021/01/12

- Improvements for OLED screensaver
- Improvements for IPv6 LAN connection
- General system stability improvements
- Fix for Dolby AC-4 audio not playing on broadcast
- Many more minor improvements

### TPM196E\_091.003.210.001– Date: 2020/10/22

- Fix for freezing picture in VOD apps
- Improvements for Ambilight + Hue
- Improvements for mesh router connection
- General system stability improvements

### TPM196E\_091.003.166.001– Date: 2020/08/11

- Screen saver improvements for OLED
- Smart TV playback fixes
- Improvements for UI / translations
- General system improvements

### TPM196E\_091.003.051.081– Date: 2020/06/08

- Fix for Finland HbbTV services
- Fix for Network connection via LAN
- Some minor improvements

### TPM196E\_091.003.051.041– Date: 2020/04/21

- Fix for HbbTV / interactive TV services not working

### TPM196E\_091.003.051.021– Date: 2020/03/30

- Improvements for no WiFi connection
- Many more minor improvements

### TPM196E\_091.002.079.021– Date: 2020/01/08

- Enables mass production of 75PUS6754/12\_CD with 2<sup>nd</sup> source panel

### TPM196E\_091.002.079.011– Date: 2019/12/19

- Enables mass production of 50PUS6554/12\_CDGOA, 50PUS6504/12\_CDGOA with 2<sup>nd</sup> source panel

**TPM196E\_091.002.223.011– Date: 2019/12/16**

- Fix for Intermittent reboots on OLED754 with language settings BG  
ATTENTION: please perform an AC off/on once after upgrading the set.

**TPM196E\_091.002.223.001– Date: 2019/10/28**

- Initial SW only for 70PUS6724

**TPM196E\_091.002.078.253– Date: 2019/10/16**

- Fix for missing page in Turksat scan
- Fix for “Philips SmartTV server not found”
- Support for new Freenet SMI+1.4/ECP CAM

**TPM196E\_091.002.078.231– Date: 2019/08/27**

- Improvement for Rakuten TV performance
- Improvements for start-up behaviour after standby

**TPM196E\_091.002.078.171– Date: 2019/07/31**

- Initial SW for OLED754 range
- Fix for wrong channel bar information
- Fix for KRS DVBC scanning time too long
- Improvements for hang-up, no reaction to RC, stuck after startup
- Improvements for network connectivity
- Improvements for UI
- Improvement for power consumption

**TPM196E\_091.002.078.111– Date: 2019/07/15**

- Initial SW for Alexa 6814 range

**TPM196E\_091.002.007.141– Date: 2019/06/27**

- Enables Rakuten TV App
- Fix for TV hangup on USB loading photo filter

**TPM196E\_091.002.007.121– Date: 2019/06/21**

- Fix for TV stuck
- Fix for home menu auto closes
- Improvement for no reaction to remote control
- Improvement for Rakuten TV performance
- Improvement for Wifi loss and no network connection

**TPM196E\_091.002.041.051– Date: 2019/06/06**

- Released for UK only, supporting FreeView Play

**TPM196E\_091.002.007.091– Date: 2019/05/24**

- Fix for Freenet installation taking too long

- Fix for set not going to standby
- Fix for Auto wake-up
- Improvement for Rakuten TV performance
- Improvement for USB stability
- Improvement for Wifi loss
- Improvement for no response to RC commands

**TPM196E\_091.002.007.051– Date: 2019/04/18**

- Initial SW for the 2K19 65x4/67x4/6804 ranges