

Software History

NOTE: Each release contains all solutions identified in the earlier version.

TPM196L_092.003.166.031 (Date published: 2020-11-17)

- Netflix loss sign in credential / No response to remote control due to memory full issue
- TV loss channel list in specific power on sequence.
- Prime video App 5.1 audio not working.
- Wireless mesh network connection issue.
- Remove detection of unsupported BT devices.
- Update CUL to v2.25.

TPM196L_092.003.155.001 (Date published: 2020-07-15)

- Resolve the BT audio issue
- Resolve the google account sign in issue with internet browser.
- General stability improvement.

TPM196L_092.003.093.061 (Date published: 2020-07-07)

- Resolve the channel loss issue.

TPM196L_092.003.093.021 (Date published: 2020-07-10)

- **Resolve the channel loss issue in Argentina.**

TPM196L_092.003.093.001 (Date published: 2020-04-23)

- Resolve the software upgrade issue due to slow network condition.

TPM196L_092.003.058.001 (Date published: 2020-04-02)

- Resolve the ambilight- follow flag not matching to default country selection issue.
- Resolve the transient noise issue when switching from TV speaker to Bluetooth sound bar issue.
- Resolve the incorrect channel number in favorite channel list issue.

TPM196L_092.003.021.001 (Date published: 2020-01-16)

- Resolve software upgrade issue.
- Resolve program locked before the setup of child lock pin code.
- Resolve the black screen issue when playing Dolby Vision video.

TPM196L_092.003.003.001 (Date published: 2019-12-16)

- Resolve Bluetooth sound distortion issue.

TPM196L_092.002.252.001

- Initial production software for Brazil and Argentina.