

## Software History

**NOTE:** Each release contains all solutions identified in the earlier version.

### **TPM196L\_092.004.071.001 (Date published: 2021-12-22)**

- TV only response to few key press on remote control after exiting Netflix.
- Bluetooth device connection issue.

### **TPM196L\_092.004.054.001 (Date published: 2021-07-23)**

- Specific HDMI Set top box no image when TV wakes up from standby issue.
- Resume not working when playback specific USB .mp4 Video
- Improvement on hang up / slow response issues.

### **TPM196L\_092.004.017.001 (Date published: 2021-03-31)**

- Argentina Analog channel no video/channel lost issue.
- Brazil DTV channel no audio issue.
- Specific Youtube video playback blinking issue.
- General stability improvement.

### **TPM196L\_092.003.166.031 (Date published: 2020-11-17)**

- Netflix loss sign in credential / No response to remote control due to memory full issue
- TV loss channel list in specific power on sequence.
- Prime video App 5.1 audio not working.
- Wireless mesh network connection issue.
- Remove detection of unsupported BT devices.
- Update CUL to v2.25.

### **TPM196L\_092.003.155.001 (Date published: 2020-07-15)**

- Resolve the BT audio issue
- Resolve the google account sign in issue with internet browser.
- General stability improvement.

### **TPM196L\_092.003.093.061 (Date published: 2020-07-07)**

- Resolve the channel loss issue.

### **TPM196L\_092.003.093.021 (Date published: 2020-07-10)**

- **Resolve the channel loss issue in Argentina.**

### **TPM196L\_092.003.093.001 (Date published: 2020-04-23)**

- Resolve the software upgrade issue due to slow network condition.

### **TPM196L\_092.003.058.001 (Date published: 2020-04-02)**

- Resolve the ambilight- follow flag not matching to default country selection issue.
- Resolve the transient noise issue when switching from TV speaker to Bluetooth sound bar issue.
- Resolve the incorrect channel number in favorite channel list issue.

### **TPM196L\_092.003.021.001 (Date published: 2020-01-16)**

- Resolve software upgrade issue.

- Resolve program locked before the setup of child lock pin code.
- Resolve the black screen issue when playing Dolby Vision video.

**TPM196L\_092.003.003.001** (*Date published: 2019-12-16*)

- Resolve Bluetooth sound distortion issue.

**TPM196L\_092.002.252.001**

- Initial production software for Brazil and Argentina.