

## Software history\_BTS7000

**Note: The filename of the bin file may NOT necessary be the same as the model number.**

The latest software solves the issues below:

### **Version 34**

TV screen version info

**V34.25.02.1310210E**

- Changed auto standby timing from 30 minutes to 15 minutes

### **Version 33**

TV screen version info

**V33.25.02.1310210E**

- Updated sound setting
- Fixed abnormal response from TV Remote Controls

### **Version 32**

TV screen version info

**V32.25.02.1310210E**

- HDMI CEC potential issue with Philips Fusion TV
- Improved HDMI CEC feature
- Device goes to standby in Audio IN mode unnecessarily
- Fixed product not waking up issue
- Updated sound setting