

Software history (BTB1370/12)

The latest software improves the below:

Note: Each release contains all solutions identified in the earlier version.

Version 1.0:

MCU V58:

- Fixed hang up issue after ECO standby.

CD V17:

- Solve the issue about gap between tracks during CD playback.