Software history(HTB3510,3511,3510X,3540,3570,3571)

Note:

- The filename of the bin file may NOT necessarily be the same as the model number.
- Each release contains all solutions identified in the earlier version.
- After updating the device, some settings such as HDMI-CEC might be erased. Refer
 to the user manual for the set-up after updating the device.

The latest software solves the issues below:

<u>Version: V1.29.02(HTB3510/12/55/98/51/94/40 HTB3511/51 HTB3510X/78 HTB3540/12/51/98/40 HTB3570/12/51/78/98/94/40/79 HTB3571/51)</u>

To ensure smoothness of SmartTV performance and improve compatibility.

Version: v1.29.01(not for /93models & HTB3511/51)

- Fix MP4 cannot playback via DLNA
- Fix keyboard display error under different languages.

Version:v1.29.00(except HTB3511/51)

Fix bug during start up

Versionv1.28.01(notfor /93models & HTB3511/51)

- Smart TV update.
- Sound output optimization.
- RDS info display error fix.

Versionv1.26.03

- Enhance playability of MP3 files
- Enhance playability of Blu-ray discs
- Improve performance related to Wi-Fi
- · Fix bug related to speaker setup
- Fix bug related to ID3 display in Russian for MP3 files
- Fix bug related to subwoofer
- Fix bug related to bass
- Fix bug related to Russian on-screen display
- Import Smart TV 2.0

Versionv1.26.02(notfor /55./78./93./94models)

- Enhance playability of MP3 files
- Enhance playability of Blu-ray discs
- · Improve performance related to Wi-Fi
- Fix bug related to speaker setup
- Fix bug related to ID3 display in Russian for MP3 files
- Fix bug related to subwoofer

- Fix bug related to bass
 Fix bug related to Russian on-screen display
 Import Smart TV 2.0

VersionV1.24.00

• Fix bugs related to HDMI ARC.

VersionV1.23.01(for HTB3510/12.3540/12.3570/12only)

• Fix bugs related to YouTube.

Note: After upgrading with the latest firmware, disconnect the device from power supply. Wait for a few seconds and then reconnect to power supply.