

Software history_HTL21x3/31x0/3142

Note: The filename of the bin file may NOT necessary be the same as the model number.

The latest software solves the issues below:

Version 35

TV screen version info
V35.25.07.140620A1

Local Display version info (will show in following sequence)

- 1) Main Version: **V35**
- 2) RISC version: **140620A1**
- 3) TX version: **V25**
- 4) RX version: **V25**
- 5) Touch Panel version: **V07**

- Reduce auto standby time to 15 minutes from 30 minutes
- Resolved source switching issue with NFC tapping
- Minor bug fixes

Version 27

TV screen version info
V27.25.07.140219A1

Local Display version info (will show in following sequence)

- 6) Main Version: **V27**
- 7) RISC version:14 **0219A1**
- 8) TX version: **V25**
- 9) RX version: **V25**
- 10) Touch Panel version: **V07**

- Resolved HDMI CEC related issues
- Fixed audio interruption noise when selecting sound modes