

Software history_HTL5140B/5145B

Note: The filename of the bin file may NOT necessary be the same as the model number.

The latest software solves the issues below:

Version 44

Local Display version info (will show in following sequence)

- 1) Main Version: **V44**
- 2) Repeater version: **V22**
- 3) TX version: **V25**
- 4) RX version: **V25**
- 5) Touch Panel version: **V08**

- Fixed Auto Standby Issue

Version 43

Local Display version info (will show in following sequence)

- 1) Main Version: **V43**
- 2) Repeater version: **V20**
- 3) TX version: **V25**
- 4) RX version: **V25**
- 5) Touch Panel version: **V08**

- Fixed Bass Setting Retention Issue

Version 42

Local Display version info (will show in following sequence)

- 1) Main Version: **V42**
- 2) Repeater version: **V20**
- 3) TX version: **V25**
- 4) RX version: **V25**
- 5) Touch Panel version: **V06**

- Updated bass setting algorithm

Version 40

Local Display version info (will show in following sequence)

- 1) Main Version: **V40**
- 2) Repeater version: **V20**
- 3) TX version: **V25**
- 4) RX version: **V25**
- 5) Touch Panel version: **V06**

- Adjusted idle standby time to 15 minutes from 30 minutes