Software history (BDP3215B/12 BDP3210B/12BDP3290B/12 BDP3290B/98)

The latest software improves the below:
NOTE: Each release contains all solutions identified in the earlier version.

Version 1.33

- Fixed the issue with noise when a disc is being ejected.