Software History

The latest software solves the issues below:

NOTE: Each release contains all solutions identified in the earlier version.

TPM52E_2.09 *(Date published: 2012-09-28)*

- EPG content update. (Only applicable to country, Portugal)

TPM52E_2.08 *(Date published: 2011-01-26)*

- Greenish picture observed after the TV exits from Teletext mode.
- The TV will not remember the last status of the picture vertical position when you adjust the position using the remote control navigation keys in the following picture formats: [Super zoom], [Subtitle zoom], [Movie expand 14:9], and [Movie expand 16:9].
- Added Turkish language option in TV menu.

TPM52E_2.07 *(Date published: 2010-11-09)*

- Empty channels are shifted to the end of the channel list. (Only applicable to country, Spain)
- The TV backlight is switched off with no onscreen display visible when TV received a channel with no picture. The backlight can be restored by activating any remote control keys except the standby key.

TPM52E_2.05 *(Date published: 2010-11-04)*

- Introduction of new product ranges (19PFL3205H/12 and 26PFL3205H/12).
- OSD translation error for Spanish language is corrected.
- Language options in the [Menu language] menu are sorted in alphabetical order.
- The video flashes/flickers while changing the screen brightness in PC mode.
- The Teletext page indicator appears randomly when the subtitle is displayed.

TPM52E_2.04 *(Date published: 2010-08-30)*

- TV turns on by itself in the presence of external interference signals, for example, by switching on the room light.
- Micro-blocks (Mosaic) observed on digital channels when using certain Conditional Access Module (CAM).
- Picture becomes dark and flickers when viewing Teletext.

TPM52E_2.03 *(Date published: 2010-07-05)*

- Addition of Russian/Polish/Spanish/Portuguese language options to the TV menu.

TPM52E_2.01 *(Date published: 2010-05-03)*

- Initial production software.