Software History (TV Software)

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:
T933E_2.05 *(Date published: 2013-10-22)*

- Romania: characters display is incorrectly in EPG menu.
- Hungary: channels are mixed.
- Ukraine: Incorrect switching from DVB-T2 signal to USB.
- Russia: When user uses Irdeto CAM (Cam connected into TV) and they tried to use USB, they could see the message: Signal is missed

T933E_2.04 *(Date published: 2013-02-06)*

- Improved channel switching time for DVB-S channels. (Only applicable to country, Turkey)
- Fixed Romania DVB-C teletext issue.

T933E_2.02 *(Date published: 2012-08-23)*

- Picture freezes while watching video from Youtube.
- Onscreen [Help] content update.
- Russian OSD translation errors are corrected.
- Changed the default [Visual impaired] option from on to off.
- Channel list update message pops up after switching channels.
- Missing satellite channels. (Only applicable to country, Germany)
- Unitymedia cable provider option is added to the DVB-C installation cable provider list. (Only applicable to country, Germany)
- TV does not response to the remote control when you switch to France 24 or Balkan TV channels via Teledünya digital service provider. (Only applicable to country, Turkey)
- Picture freezes and TV does not response to the remote control when you switch to Mezzo channel. (Only applicable to country, Serbia)

T933E_2.00 *(Date published: 2012-07-13)*

- Initial production software.

Software History (DVD Software)

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

R20G *(Date published: 2012-07-18)*

- Corrected the file name to "KDR071.BIN" under [Version info].

R20B *(Date published: 2012-07-13)*

- Initial production software.