Software History

NOTE: Each release contains all solutions identified in the earlier version.
The latest software solves the issues below:

TPM1013E_003.020.000.001 *(Date published: 2018-07-18)*
- [SmarTV] Device portal change to Zeasn.

TPM1013E_003.015.000.001 *(Date published: 2015-12-17)*
- Issue fix: AVI, MKV and MP3 files from USB playback issue.
- Issue fix: Skype is not working.

TPM1013E_003.012.000.001 *(Date published: 2015-01-13)*
- KDG PVR recording fails.
- HTML5 apps cannot be opened from the dashboard.
- Inconsistent TV clock, when switch between "Automatic" and "Country dependent".

TPM1013E_003.011.000.001 *(Date published: 2014-08-27)*
- Skype update.
- Issue fix: VOD Maxdome.
- Issue fix: (France, Denmark, Poland) HbbTV "ANT.galiobrowser" popping up.
- Issue fix: (Denmark, Finland) HbbTV is not working on DR channels.
- Issue fix: (France) HBBTV issue with channel M6.
- Issue fix: Error message shown when loading Netflix.
- Issue fix: No timeshift while HbbTV is active.

TPM1013E_003.010.000.001 *(Date published: 2014-06-13)*
- Issue fix: Worldcup Ambilight app support for 2K13 Smart TV model.
- Issue fix: TV responses slow when switching channels.

TPM1013E_003.009.000.001 *(Date published: 2014-05-26)*
- Issue fix: Auto-fill setting.
- Issue fix: Improvement of RC slow reaction when there are DVB-S channels installed.
- Issue fix: HDMI ARC OSD message permanently shown up.

TPM1013E_003.007.000.001 *(Date published: 2014-04-10)*
- Issue fix: (French) Sets blocked, frequently on BFM and M6.
- Issue fix: Picture is cut off when playing video clips from USB.
- Issue fix: (Russian) Capital letter issue.
- Issue fix: Security on SmartTV set.

TPM1013E_003.005.000.001 *(Date published: 2014-03-10)*
- Issue fix: In HBBTV the volume bar do no show, but can adjust volume.
- Issue fix: The volume indicator is not displayed, but can adjust volume.
- Issue fix: VoD buffers & stops playback in TPM10 (**maxdome and watchever**).
- Issue fix: (DE) Skype menus in wrong language since 3.1.0.1.
- Issue fix: (DACH) Unicable is not working well.

- Issue fix: (Ukraine) TV cannot recode channel both in DVB-T2 and in cable TV.
- Issue fix: (Ukraine) cannot type "space" symbol from on-screen keyboard in SmartTV mode.
- Issue fix: (Ukrainian and Russian) Language in Smart TV, input of capital letters are not correct.
- Issue fix: TV will hang up when entering Hbb TV menu.
- Issue fix: Repetitive OSD "channel-update is available in std.-by".
- Issue fix: T2 channel no sound output.

TPM1013E_003.002.000.001 *(Date published: 2014-02-12)*
- [NetTV apps] TV hang-up after video playback in MEGOGO apps.
- Issue fix: Duplicate channels detection on DVB-T.
- Issue fix: Subtitles in Netflix are unreadable.
- Issue fix: (Russia) DVB_T2 reception failed.
- Issue fix: (Spain) When the customer watching TV, he/she gets the message to enter pin code.
- Issue fix: (Ukraine) viewing of .JPG pictures from USB issue. Some pictures in .JPG format cannot be viewed correctly on TV screen.

TPM1013E_003.001.000.001 *(Date published: 2013-12-12)*
- Sami Subtitle[SF Anytime app]: Sami subtitles are not displayed during movie playback
- No video when playback MPEG-DASH clear content but audio is heard
- Implement NetTV library V2.08
- Ziggo E-sticker icon update
- Issue fix: TV not waking up from standby when setting a PVR
- Issue fix: DVB-S/ set does return to last program status after stand by
- Issue fix: TV boots up with no picture, only audio, when switched on from loungelight.
- Issue fix: SmartTV hangs after 5-10 sec rewinding
- Issue fix: Russian Cyrillic "абвг" letters isn't working in SMART TV Internet browser

TPM1013E_003.000.000.001 *(Date published: 2013-10-14)*
- Implemented NetTV library V2.05
- Synchronized Ziggo(VOD) certification solution
- Added Telenet broadcast certification: When a channel scan is performed from the TV menu, no digital channels are found when the parameters are not reset.
- Feature implementation: Miracast function with Samsung S4 and LG Nexus mobile phone
- Feature implementation:
    - YTLB (V3 to V4)
    - HBBTV
    - MyRemote (without scheduled-recording function)
    - Multiroom-client

TPM1013E_002.030.000.001 *(Date published: 2013-10-02)*
- Added NetTV library V1.05.2 for solution of Germany/Turkey Smart TV reboot issue in DVB-S input
- Solution for 55PFL4908H in which 3D is not working correctly

TPM1013E_002.025.000.001 *(Date published: 2013-08-07)*
- Fixed Belgium missing DTV channel issue
- Slovenia -DVB-T scan with country SLOVENIA: DVB-T channels are located from program number 800+

- Canal Digital certification award and e-sticker enabled.
- Update Slovenia language translation
- Skype no function after SW V2.023 upgrade via autorun.upg
- Backlight dimming modification for TXT subtitle
- Issue fix: Unity media certification logo is shown for Country Netherlands instead of UPC certification logo.
- Issue fix: Analogue channels inside additional settings for DVB-T scan, country Slovenia, should be OFF by default.
- Issue fix: A HELP menu »?« – electronic user manual – database is empty/nothing is shown on the screen.
- Issue fix: OSD keyboard should appear in local languages (see Done, Hide, Backspace,…).
- Issue fix: DLNA server error message: Se below. This is not true. All other connected devices can play all content.
- Issue fix: Telenet issue- DVB-C CAM menu does not allow confirmation of entered Network ID.
- Issue fix: Telenet issue - No network ID can be entered when starting a channel scan.
- NetTV library 1.05 implementation
- Hebrew language implementation
- Field issue: Error 500 while opening IP EPG
- Field Issue: [Ziggo] Pin Pop Up is displayed when exiting VOD or inserting CAM or channel switching
- Field issue: Network Data Update YES/NO issue
- Field issue: Loading of SmartTV portal during 6am update
- Field issue: No signal when connect to special STB (Turkey)
- Field issue: Broadcast EPG DVB-S: First program cannot be selected
- Field Issue: Update UI translation for Germany request (DivX UI in Content browser)
- NetTV App improvement - Wuaki TV app issue
- Skype kit 4.5 implementation
- BBC iplayer certification

TPM1013E_002.021.000.001 *(Date published: 2013-05-22)*
- Introduction of new product ranges (22" and 24" series).
- Improvement on Wi-Fi connection.
- Improvement on 3D video. (Only applicable to 3D models)
- Virtual keyboard is removed after access Smart TV.
- Updated onscreen help content.
- Updated predefined channel list for Austria.
- Corrected OSD errors for Portuguese language.
- Added translations for software upgrade EULA (End User License Agreement)

TPM1013E_002.016.000.001 *(Date published: 2013-04-24)*
- New software release for production purpose.

TPM1013E_002.015.000.001 *(Date published: 2013-04-04)*
- Fixed Ziggo CI+ module not working issue. (Only applicable to country, Netherlands)
- Unable to toggle between uppercase/lowercase/numerical while using onscreen keyboard during wireless installation.
- You can now upgrade your TV software via [Setup] > [Update software] > [TV with internet] if your TV is connected to internet.

TPM1013E_002.014.000.001 *(Date published: 2013-03-27)*
- With this software your TV is now certified for Boxer HD, RiksTV, Com Hem, and Soarview. (Only applicable to T-models)
- Solved flickering picture in Auto fill picture format for analog channel.
- Solved the channel sorting issue. (Only applicable to country, France)
- Corrected the Wi-Fi Miracast display name.
- Improved channel switching time for DVB-S channels. (Only applicable to country, Turkey)
- Fixed Romania DVB-C teletext issue.

TPM1013E_002.007.000.001 *(Date published: 2013-03-06)*
- Initial production software for K-models.

TPM1013E_002.004.000.001 *(Date published: 2013-03-06)*
- Initial production software for H-models.