Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPN141A_034.003.018.128 *(Date published: 2015-03-26)*
- Slow reaction on RC commands.

TPN141A_034.003.016.128 *(Date published: 2015-02-02)*
- Smart TV could not login.

TPN141A_034.003.008.128 *(Date published: 2014-09-26)*
- Skype update.

TPN141A_034.002.006.128 *(Date published: 2014-06-16)*
- To disable automatic power saving mode when TV is used as a SMART TV monitor display.

TPN141A_034.002.003.128 *(Date published: 2014-04-22)*
- Initial production software.