Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

43PFS4012-12_SW V1.1.9(MSD3463_S_SN51_69.bin)*(Date published: 2017-09-26)*
• Improvement on DVB-S channel installation without predefined channel list.
• Improvement on options of Scan type for DVB-S signal.
• Improvement on some OSD translations for Germany/Slovenia/Poland.
• Improvement on some EDFU translations for Poland.
• Improvement on adding Vodafone operator for DVB-C signal.
• Improvement on adding selected options(legacy and unicable)for Unicable installation.
• Improvement on adding Channel update installation for DVB-S+DVB-C+DVB-T2.
• Improvement on revising some functions of Recording playback.
• Improvement on revising the function of second Channel installation for DVB-C signal.
• Improvement on revising the OSD tips from "NO SIGNAL" to "No digital channels installed" if no DVB-C channels installed for Germany.
• Improvement on adding the function that pressing both "back" key or " Exit" key of the Remote Control can exit EPG Guide.
• Improvement on adding the function that after finishing tuning setup for DVB-T2 signal, there will be a summary of new found channels.
• Improvement on revising Channel installation of "only free channels".