Software History

Philips 2K20 6815 – ranges

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPM207E_202.003.131.001 *(Date published: 2021-06-10)*
- Improvements for system stability.
- Improved screen mirroring connectivity.
- General improvements.

TPM207E_202.003.039.001 *(Date published: 2021-06-07)*
- Wifi connection process improvement.
- General improvements.

TPM207E_202.002.167.051 *(Date published: 2020-07-28)*
- Initial production software.