Software history – Philips 2K19 65x4/67x4/6804/6814/OLED754 ranges

TPM196E_091.004.086.001– Date: 2022/11/21
- Stability improvements
- Many more minor improvements

TPM196E_091.004.086.001– Date: 2022/06/07
- Improvements for Ambilight Hue
- Stability improvements
- Many more minor improvements

TPM196E_091.004.078.011– Date: 2022/02/24
- Fix for not working Ambilight after standby state

TPM196E_091.004.078.001– Date: 2022/02/11
- Improvements for Ambilight Hue
- Improvements for not react to Alexa
- Stability improvements
- Many more minor improvements

TPM196E_091.004.070.001– Date: 2021/11/25
- Fix for unexpected TV startup
- Fix for unexpected TV reboots
- Fix for audio loss via HDMI ARC
- Fix for switches back to previous channel after changing channels
- Improvements for VOD services performance
- Improvements to connection with Philips Smart TV Server
- Stability improvements
- Many more minor improvements

TPM196E_091.004.061.001– Date: 2021/08/31
- Fix for no response on RC commands
- Fix for unexpected start of screensaver
- Miracast improvements
- Youtube casting improvements
- Improved connection with 4K set top boxes
- Stability improvements
- Updated DVB-S Swiss predefined list
- Many more minor improvements

TPM196E_091.004.027.011– Date: 2021/05/09
- Fix for no picture with some specific set top boxes

TPM196E_091.004.027.001– Date: 2021/04/09
- Changes on preinstalled apps and search engine in internet browser when Russia is chosen as installation country
- Improvements for live stream playback in apps
- Improvements on Ambilight + Hue
- Improvements for no reaction on RC buttons when hbbTV is enabled
- Many more minor improvements
- General system stability improvements

TPM196E_091.003.255.001– Date: 2021/01/12

- Improvements for OLED screensaver
- Improvements for IPv6 LAN connection
- General system stability improvements
- Fix for Dolby AC-4 audio not playing on broadcast
- Many more minor improvements

TPM196E_091.003.210.001– Date: 2020/10/22

- Fix for freezing picture in VOD apps
- Improvements for Ambilight + Hue
- Improvements for mesh router connection
- General system stability improvements

TPM196E_091.003.166.001– Date: 2020/08/11

- Screen saver improvements for OLED
- Smart TV playback fixes
- Improvements for UI / translations
- General system improvements

TPM196E_091.003.051.081– Date: 2020/06/08

- Fix for Finland HbbTV services
- Fix for Network connection via LAN
- Some minor improvements

TPM196E_091.003.051.041– Date: 2020/04/21

- Fix for HbbTV / interactive TV services not working

TPM196E_091.003.051.021– Date: 2020/03/30

- Improvements for no WiFi connection
- Many more minor improvements

TPM196E_091.002.079.021– Date: 2020/01/08

- Enables mass production of 75PUS6754/12_CD with 2nd source panel

TPM196E_091.002.079.011– Date: 2019/12/19

- Enables mass production of 50PUS6554/12_CDGOA, 50PUS6504/12_CDGOA with 2nd source panel

TPM196E_091.002.223.011– Date: 2019/12/16

- Fix for Intermittent reboots on OLED754 with language settings BG
  ATTENTION: please perform an AC off/on once after upgrading the set.

TPM196E_091.002.223.001– Date: 2019/10/28

- Initial SW only for 70PUS6724

TPM196E_091.002.078.253– Date: 2019/10/16

- Fix for missing page in Turksat scan
- Fix for "Philips SmartTV server not found"
- Support for new Freenet SMiT CI+1.4/ECP CAM

TPM196E_091.002.078.231– Date: 2019/08/27

- Improvement for Rakuten TV performance
- Improvements for start-up behaviour after standby

TPM196E_091.002.078.171– Date: 2019/07/31

- Initial SW for OLED754 range
- Fix for wrong channel bar information
- Fix for KRS DVBC scanning time too long
- Improvements for hang-up, no reaction to RC, stuck after startup
- Improvements for network connectivity
- Improvements for UI
- Improvement for power consumption

TPM196E_091.002.078.111– Date: 2019/07/15

- Initial SW for Alexa 6814 range

TPM196E_091.002.007.141– Date: 2019/06/27

- Enables Rakuten TV App
- Fix for TV hangup on USB loading photo filter

TPM196E_091.002.007.121– Date: 2019/06/21

- Fix for TV stuck
- Fix for home menu auto closes
- Improvement for no reaction to remote control
- Improvement for Rakuten TV performance
- Improvement for Wifi loss and no network connection

TPM196E_091.002.041.051– Date: 2019/06/06

- Released for UK only, supporting FreeView Play

TPM196E_091.002.007.091– Date: 2019/05/24

- Fix for Freenet installation taking too long
- Fix for set not going to standby
- Fix for Auto wake-up
- Improvement for Rakuten TV performance
- Improvement for USB stability
- Improvement for Wifi loss
- Improvement for no response to RC commands

TPM196E_091.002.007.051– Date: 2019/04/18

- Initial SW for the 2K19 65x4/67x4/6804 ranges