Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPM206E_201.003.160.001 *(Date published: 2021-11-02)*
- Fix for Hue not follow Ambilight
- Improvements for internet browser performance
- Improvements on WIFI connection stability
- Improvements for wireless mesh networking
- Improvements on Smart TV app performance
- Improvements for Alexa
- Miracast improvements
- System stability improvements
- General and stability improvements
- TV performance improved.

TPM206E_201.002.252.001 *(Date published: 2020-11-10)*
- Initial production software.