Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPM215E_001.001.220.202 *(Date published: 2022-05-09)*
- Improvements on system stability.
- Improvements for system speed

TPM215E_001.001.109.002 *(Date published: 2021-12-08)*
- Feature improved in screen mirroring when TV connected to 5GHz
- Picture abnormal improved when mobile cast the live program of Facebook app to TV.

TPM215E_001.001.109.001 *(Date published: 2021-11-23)*
- TV has sound but no picture.
- General system improvement

TPM215E_001.001.070.000 *(Date published: 2021-06-20)*
- General system improvement

TPM215E_001.001.041.001 *(Date published: 2021-05-10)*
- Initial production software.