Software History

NOTE: Each release contains all solutions identified in the earlier version.

TPN206L_204.002.127.001 (Date Published: 28 Dec 2022)
- Dolby Vision USB video playback no video.
- DRM video playback issue in Globo Play app.
- Youtube purchased video playback issue.

TPN206L_204.002.123.001 (Date Published: 16 Aug 2022)
- Not able to open the IPTV channels video using the Clouddy App
- TV reboot when play video in Red Bull App.
- Cable analog channel change issue with combination of direct digit keys and CH+/- keys.

TPN206L_204.002.118.001 (Date Published: 9 Jun 2022)
- Youtube app keep loading but not started in specific conditions.
- TV shows wrong hour information in home screen.
- Pink image when customer uses RGB color space and active HDR in PC.
- USB video with external subtitles (.srt) are shown in one line instead of two.
- PS5 image flashing.
- In Cable Analog channels, using CH+/- key to increment channel, TV jumps from ch18 to 70
- In specific SBT channel, TV selects the wrong audio track without sound.

TPN206L_204.002.110.001 (Date Published: 7 Dec 2021)
- TV start up issue due to specific memory location corruption issue.
- TV freezes in specific use case.
- Internet Browser crashes shortly after open specific URL address
- SS IPTV app start up issue.
- TV does not save the change in the picture settings after exiting the Youtube/Netflix App.
- HDMI Ultra HD setting menu translation issue

TPN206L_204.002.102.001 (Date Published: 11 Aug 2021)
- Add Globoplay native App
- Translation issues.
- TV hang up and reboot due to incorrect max_ATV_channel data error.

TPN206L_204.002.092.001 (Date Published: 14 Apr 2021)
- TV hang up and reboot in specific programs in Globo channel in Brazil.
- TV shows black screen and no response to RC after power off and on in Netflix.
- Bluetooth device connection issue.
- Missing "Dolby Atmos" notification message when playback Dolby Atmos contents.
- Not able to reset the picture and sound styles on some smart TV APPs.

TPN206L_204.002.090.001 (Date Published: 16 Mar 2021)
- Analog alternate audio issue.
- Screen Mirroring issue
- Bluetooth pairing issue

- Time zone issue.

TPN206L_204.002.082.001 (Date Published: 23 Dec 2020)
- Update PQ for new model.
- WIFI password encryption.
- General improvements.

Note: After software update, TV may prompt for network connection due to the change in WIfi password encryption in this software.

TPN206L_204.002.071.031
- First software release.