Software History

NOTE: Each release contains all solutions identified in the earlier version.

TPM186E_018.004.076.001 (Date published: 2018-12-01)
- Resolve You Tube screen off mode wake up issue
- Resolve device portal connection issue reported in some retail outlets.
- Resolve the timeshift playback control bar display issue.

TPM186E_018.004.007.031 (Date published: 2018-09-24)
- Resolve wifi module queue block issue.
- Resolve UK FVP issues.
- Add Russia NTV+ and Tricolor Satellite package installation.
- Resolve HbbTV issues
- General stability improvement.

TPM186E_018.002.211.001 (Date published: 2018-07-18)
- Resolve subtitle off issue in UPC Switzerland.
- Resolve DVB-S channel lost issue in Switzerland.
- Reduce the scanning time of Telemach DVB-C channel installation in Slovenia.
- General Stability improvement
- Network connectivity improvement
- Resolve UI translation issues.
- Remove unused data in buffer memory

TPM186E_018.002.108.041 *(Date published: 2018-05-18)*
- modified panel parameter to solve 49PUS6803/12 vertical line noise issue.

TPM186E_018.002.108.011 (Date published: 2018-04-24)
- Support UK FVP.
- Support Albanian Language
- General Stability improvement
- eUM (electronic User Manual) update
- Resolve UI translation issues.

TPM186E_018.002.023.031 *(Date published: 2018-03-22)*
- modified panel parameter to solve 55PUS6503/12 picture flicker issue.

TPM186E_018.002.023.021 *(Date published: 2018-02-23)*
- Initial production software.