Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPM191E_101.001.145.003 *(Date published: 2020-12-22)*
• [Wifi] support 5G (band 4) WiFi network.

TPM191E_101.001.145.001 *(Date published: 2020-11-03)*
• [Wifi] support 802.11r mesh WiFi network.
• [Netflix] ATMOS sound quality improve.

TPM191E_001.004.097.000 *(Date published: 2020-07-21)*
• [Android] System optimization.
Note: This is switch from 2K19 to 2K20 SW version.

TPM191E_001.004.087.000 *(Date published: 2020-05-13)*
• Dolby vision notification=on, but it can't show "Dolby vision".

TPM191E_001.004.052.000 *(Date published: 2020-03-13)*
• [App_iQiY] Lip sync issue.

TPM191E_001.003.200.003 *(Date published: 2020-01-22)*
• Bluetooth remote control software upgrade
• [App_Netflix] Dolby ATMOS & Sunrise function.

TPM191E_001.002.182.001 *(Date published: 2019-12-11)*
• Improvements for Bluetooth remote control pairing.

TPM191E_001.001.114.002 *(Date published: 2019-10-23)*
• [App_Youtube] TV can wake up from standby when cast Youtube.
• TV has no picture with audio output after switch source from HDMI with Dolby vision signal to other source.

TPM191E_001.001.095.001 *(Date published: 2019-09-14)*
• Initial production software.