PHILIPS firmware update

Model: BDP1502/F7 A, B

This update is for the BDP1502/F7 A and BDP1502/F7 B.

When this file is downloaded, the file is a zip file whose name is BDP1502A.

You will need to unzip the file using a program such as the zip program in windows.

The file can be loaded using a USB drive or by burning the file onto a CD. If burning to a CD, the CD must be finalized.

Updating:

1. Turn the power on and insert the USB drive or CD. The following screen will appear.


2. Press the [HOME] button on the remote, select Setup and press OK.
3. Select – Advanced – Software Update – Disc or USB. Press OK and the following screen will appear.

More on the next page.

4. The Firmware update will start as shown.

   DO NOT PRESS AN BUTTONS OR REMOVE POWER WHILE THE UPDATE IS IN PROGRESS AS IT MAY DAMAGE THE UNIT.

5. After the update, the power will turn off and back on automatically. Remove the disc or USB drive.

FIRMWARE UPDATE HISTORY

DATE	VERSION	FIX
07/13/21	ECU03UL_10107	Memory issues
04/08/22	ECU03UL_10108	Changed factory test mode