

Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

QM152E_000.007.070.000 *(Date published: 2018-09-10)*

- Improve playability with device SONY PS4 PRO/SONY FMP-X10memory
- Google security improvements
- Channel logo updates

QM152E_000.007.058.000 *(Date published: 2018-06-04)*

- TV is repeatedly displaying a notification that it's running low on memory
- Google security improvements
- Channel logo updates

QM152E_000.007.040.000 *(Date published: 2018-02-12)*

- Solves APK side-loading issue
- Channel logo updates

QM152E_000.007.013.000 *(Date published: 2017-11-16)*

- No Audio in APPs (when switching between source HDMI and Smart TV)
- Security patch for WiFi - WPA2 protocol
- Channel logo updates

QM152E_000.005.255.246 *(Date published: 2017-09-21)*

- Google security improvements
- Stability improvements
- No Audio during YouTube playback (when TV Tuner is not installed)

QM152E_000.005.255.224 *(Date published: 2017-08-08)*

- Solves "Unfortunately, the Teletext application has stopped working" (Czech)
- New automatic upgrade feature (not applicable for 6500 and 6800 range)
- Channel logo updates

QM152E_000.005.255.197 *(Date re-published: 2017-06-22)*

- Solution for Lip Sync
- Channel logo updates
- Stability Improvement
- Improvement in APP [SPB TV Россия] (Russia)
- Improvement in DVB-S installation (Russia)
- Improvement in DVB-T profile setting (Croatia)

QM152E_000.005.255.171 *(Date re-published: 2017-05-08)*

- Stability Improvement
- Solution for Videotext "888" and "889" not getting re-enabled after commercial break
- Solution for Macedonian subtitles reverting to Serbian subtitles after each channel change
- Update Predefined lists for Germany FTA and HD+
- Introduction of "How-To" app and re-arranged Settings shelf
- Improvement in UI captions translation (Dutch)

QM152E_000.005.255.133 *(Date published: 2017-03-09)*

- Sound drop/distortion via ARC
- APP improvement (Videoland)
- Stability Improvement

QM152E_000.005.255.114 *(Date published: 2017-01-12)*

- Picture Quality improvement
- User Interface menu improvement (Light Sensor)
- Stability Improvement
- Teletext (Sweden)
- Picture is compressed in HDMI source

QM152E_000.005.255.090 *(Date published: 2016-11-09)*

- Lost of picture setting after Standby
- Support Digiturk STB (Country Turkey)
- Improvement in Wifi performance
- Improvement channel loss [DVB-C]
- Improvement smooth streaming issue [Chili TV app]
- Update channel logo channel 'Q2 HD'

QM152E_000.005.234.014 *(Date published: 2016-07-26)*

- BT Remote Control stop operating after some time (6500 range)

QM152E_000.005.234.013 *(Date published: 2016-06-17)*

- TV wakes up at 4.00/6.00 AM

QM152E_000.005.234.010 *(Date published: 2016-04-28)*

- Voice search via Android TV Remote Control APPs
- Videociety APPs improvement
- Audio drops out when in Broadcast
- Swiss channel list update
- BT Remote Control Pairing/lost connection
- 12 Hr silent Reboot (6400 series)
- Lip Sync seen in DVB-S scrambled channel

QM152E_000.005.210.000 *(Date published: 2016-03-17)*

- New Homing frequency for YouSee (Denmark)
- Power key on Joystick behaves the same as power key on RC
- Pulsating standby LED when TV is starting up but not yet ready to receive RC commands
- Miracast selection for 6400 series
- User defined PNM settings are not retained for YouTube playback
- Netflix shows abnormal video during playback
- Stability improvement

QM152E_000.005.101.054 *(Date published: 2016-02-03)*

- Loss of tuner menu entries/not able to do channel search
- Distorted/bad audio via HDMI

QM152E_000.005.101.047 *(Date published: 2016-01-08)*

- BBCi Certification
- Incorrect CI+ key error message appearing when CI function is not enabled
- Incorporate Google latest security update

QM152E_000.005.100.044 *(Date published: 2015-12-09)*

- Hang up during AVI playback

- PlayStore closes upon selection
- TV reboots
- HD picture playback, vertical stripe on the right edge (5500 series)
- Color temperature last status not stored when TV starts up from standby
- Scart connection: No picture after start up from standby
- Russia cable - "no signal" OSD shown when switching from analog to digital channels
- Russia – unable to find DVB-T2 mux (666MHz) during auto-search
- Serbia country New channel logos updated
- Sporadic no backlight after set start up (6400 series)

QM152E_000.004.045.004 *(Date published: 2015-11-02)*

- HDCP 2.2 support for 24/25/30Hz 4K content
- Improve Color Temperature setting does not remember after AC off/on.

QM152E_000.004.045.001 *(Date published: 2015-09-22)*

- Improve HDMI ARC lip sync in Germany
- Fixed set go back to standby automatically

QM152E_000.004.038.000 *(Date published: 2015-09-09) only for 6400 series*

- Improve lip sync issue in Netherlands

QM152E_000.004.024.000 *(Date published: 2015-08-24) only for 6400 series*

- Support Netflix 4K

QM152E_000.003.222.081 *(Date published: 2015-07-21) only for 6400 series*

- Initial production software.

QM152E_0.3.222.79 *(Date published: 2015-07-23) only for 5500/6500 series*

- Improvement on overnight standby issue.
- Support Netflix 2K

QM152E_0.3.222.68 *(Date published: 2015-07-14) only for 5500/6500 series*

- Initial production software.