

## Software history

### Main modifications

#### Each release contains:

- All solutions identified in earlier versions.
- Due to our global IT structure, there might be a delay in the uploading/synchronising of new SW releases (and their release notes).
- Please, have a little patience if you cannot immediately see the new files on our web pages and try some hours later.
- Besides general improvements on functionality and performance, this latest software solves the issues below:

#### Q555x\_x.14.105.0 (Date published: 2013-07-25)

- Extend 6AM signon spread with 2 hours: The 6AM wake up of the TV sets are spread over larger period in time between 4AM and 6AM.
- DVB-S update predefined channel list for Sky: Preferred list of channels updated ( only of reinstall)
- HDMI blanking with UPC Horizon box: Video and audio drop outs with UPC Horizon box solved.
- Switzerland, cable ESR Sion set is blocked: Unable to install free to air channels together with scrambled channels.
- ECD signon blocked due to wrong version handling: Future improvement sign on behavior Smart TV.

#### Q555x\_x.14.104.0 (Date published: 2012-11-26)

- HbbTV application is not working.  
(Only applicable to country, Czech Republic)
- USB recording resume function is not working.

#### Q555x\_x.14.101.0 (Date published: 2012-09-27)

- Subtitle is not synchronized with the video.
- Subtitle is shown in strange colours.

#### Q555x\_x.14.99.0 (Date published: 2012-07-17)

- Content from maxdome is distorted in autozoom on a 16:9 set.
- Set blocked when subtitle menu is opened and HbbTV is present.
- Videociety streaming is causing a TV crash.
- TV switches on with Perfect Natural Motion switched on by default. The user has to switch off PNM each time if they don't want it.
- Improvement on picture performance.

**Q555x\_x.14.98.0** (Date published: 2012-05-07)

- Solution for audio mute when signal is dolby/AC3.
- Solution for video audio out of sync.
- Solution for UPC in Hungary resulting in no channels installed after installation.

**Q555x\_x.14.97.0** (Date published: 2012-04-19)

- Solution for wrong chars on DVB-S Czech EPG.
- Solution for TV switches to standby within a few minutes .
- Solution for intermittent set reboots mainly in DVB-S.
- Solution so that the DVB-S cam module is accessible via the option menu.

**Q555x\_x.14.96.0** (Date published: 2012-03-02)

- 3D format option not enabled in TV3 HD during 3D broadcasting.(Spain)
- Strange signs in 'Multi View' visible.
- No support of certain HD and 3D channels via CI Card of DSMART.(Turkey)
- Automatic sorting of DVB-S channels not possible anymore.
- Intermittent scrambled program via Ziggo CI+.
- issues with German translation in the menu "sortieren".

**Q555x\_x.14.95.0** (Date published: 2012-02-01)

- Added an option to disable the deletion of channels in background install. (Only applicable to K-models)
- Teletext is not working on ZIGGO channel. (Only applicable to country, Netherlands)
- Ambilight flashes intermittently.
- Movie stops by itself when you watch a rented movie from an online video store.
- Unable to activate MHEG (with the red button) on a MHEG channel.

**Q555x\_x.14.93.0** (Publication date : 2011-12-21)

- Solution stuttering noise on HDMI.

**Q555x\_x.14.91.0** (Publication date : 2011-12-13)

- Solution Metallic sound when switching between SD and HD sources.
- Solution about visible artefacts on the 46PFL9706.
- Solution for no sound from HTS when preset changed from DVB-C to analoge cable.
- Solution for set hangs in semi-standby after switch off,coming from standby.
- Solution for set goes to standby after exact 2 hours.
- Solution about startup of the set the splash screen comes up,a reboot happens and the splash screen comes up again.
- Solution for set startup with sound and ambilight but no picture.

- Solution for sound drop when connected via HDMI.
- Solution for video continuously stutters in H264 services DVB-T.
- Solution for No HD+services anymore possible when provider driven SW update is done.(Germany,Austria and Switzerland)

**Q555x\_x.14.84.0** (Publication date : 2011-10-19)

- Solution about picture disappearing while watching via Ziggo DVB-C CI+.
- Solution about not starting RTL-XL programs in The Netherlands via NetTV.
- Improvement for PVR recording.
- Solution for intermittently hot rebooting.

**Q555x\_x.14.80.0** (Publication date : 2011-10-11)

- Solution for the 32PFL9606 to have audio/video at playback of recording.
- Solution for the 32PFL9606 that during fast forward the record jumps to the beginning.
- Improvement in programmed recordings.
- Improved starting up behavior.
- Improvement for the 32PFL9606 regarding 3D in content browser.

**Q555x\_x.14.79.0** (Publication date : 2011-10-07)

- Adding the new feature "You Tube Leanback".  
<http://www.youtube.com/watch?v=bitse42LpKA>
- Solution to have better performance during use of USB mouse and keyboard.
- Improvement on speed level during HDD testing.
- Solution when using low quality SD cards with Video store.
- Improvement by using PVR:Recording.
- Solution for scrambled recording in France.
- Solution for startup sequence HDD/TV.
- Solution for video freeze during Timeshift.
- Solution for picture disturbances on DVB-C channel "Phoenix".

**Q5551\_11.10.105.1** (Publication date: 2011-08-23)

- Improvement in this version is for provider compliance.

**Q5551\_11.9.22.0** (Publication date: 2011-07-15)

- Solution for the Nandflash issue stopping at 80%. Overload at partition of the Nand flash.
- Solution so that the WISI STB is supported.
- Solution to avoid when Nettv and Sat are connected no menu navigation is possible the first 2 - 3 minutes.
- Solution to avoid that there is no TXT after open internet in NetTV.
- Solution so that teletext is displayed correctly in External 1 when switch from Digital RF.
- Solving the Russian translation errors in UI and Net TV.

- Solution not losing the presets anymore after toggling between ASTRA and HOT Bird (between 2LNBs).
- Solution so that with the ORF HD Cam no black pictures are seen anymore.
- Solution for picture disturbance on DVB-C channel 'Phoenix' - Germany region Zweibrucken.
- Solution about Lipsync on EXT, 'audio uitvoer delay' not working.
- Solution when starting up sometimes no picture.

**Q5551\_11.9.18.0** (Publication date: 2011-05-11)

- Solution for special characters in Portuguese multitablet via RC.
- Solution for EPG starts always on channel 1.
- Solution for problems with technisat HD8+ HD stb.
- Solution for movie in videostore stops after 2h33.
- Small picture of TV channel in right upper corner after going to NetTV.
- Solution for the word "Select your language" in virgin installation page in Portuguese language.
- Solution for the word "Noise Reduction" in Portuguese for all the smart settings in watch demo.
- less intense OSD remains on screen (40/46PFL9715)
- Remove dependency on channellib (and other libs) from Software Upgrade.
- Solution for Channelmap incompatibility.