

Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPM215E_101.000.198.110 (*Date published: 2022-12-26*)

- Improved no sound from soundbar when turning on TV.
- Android Q2R software release.
- Android security patches: November 5th 2022.

TPM215E_001.001.220.211 (*Date published: 2022-10-03*)

- Improved HDMI compatibility
- It shows "Retrieving Data..." in DTV Thailand.
- Improvements on system stability.

TPM215E_001.001.220.206 (*Date published: 2022-07-25*)

- Add meWatch feature for /98.

TPM215E_001.001.220.202 (*Date published: 2022-05-09*)

- Improvements on system stability.
- Improvements for system speed.
- Improvements for wifi connection.

TPM215E_001.001.109.002 (*Date published: 2021-12-08*)

- Feature improved in screen mirroring when TV connected to 5GHz
- Picture abnormal improved when mobile cast the live program of Facebook app to TV.

TPM215E_001.001.109.001 (*Date published: 2021-11-23*)

- TV has sound but no picture.
- General system improvement

TPM215E_001.001.070.000 (*Date published: 2021-06-20*)

- General system improvement

TPM215E_001.001.041.001 (*Date published: 2021-05-10*)

- Initial production software.