

## Software History

**NOTE:** Each release contains all solutions identified in the earlier version.  
The latest software solves the issues below:

### **TPM1011E\_003.004.000.001** *(Date published: 2014-09-03)*

- Update e-DFU.

### **TPM1011E\_003.003.000.001** *(Date published: 2014-05-15)*

- Fixed: (French) Sets blocked frequently on BFM and M6.
- Fixed: Picture is cut off when playing video clips from USB.
- Fixed: (DACH) Unicable is not working well.
- Fixed: Repetitive OSD "channel-update is available in std.-by".
- Fixed: Autofill setting
- Fixed: HDMI ARC OSD message permanently shown up.

### **TPM1011E\_003.001.000.001** *(Date published: 2014-03-20)*

- Fixed: (Russia) DVB\_T2 reception failed.
- Fixed: (Spain) Pin code issue.
- Fixed: (Ukraine) JPG format cannot be viewed correctly on TV screen.
- Fixed: No video when playback MPEG-DASH clear content.
- Fixed: TV not waking up from standby when setting a PVR.
- Fixed: DVB-S set does return to last program status after std.by.
- Fixed: TV boots up with no picture, only audio, when switched on from loungelight.
- Fixed: (Finland) analog channel not detected on DVB-C.
- No digital channels are found when the parameters are not reset.

### **TPM1011E\_002.009.000.001** *(Date published: 2013-09-27)*

(Note: Included fixes implemented in test releases from V2.06 to V2.08)

- Updated translation in Finnish language
- Hebrew language implementation
- Updated UI translation for Germany
- No signal when connect to special STB (Turkey)
- A HELP menu »?« – electronic user manual – database is empty/nothing is shown on the screen.
- OSD keyboard should appear in local languages

### **TPM1011E\_002.005.000.001** *(Date published: 2013-05-27)*

- Initial production software.