

Software history

The latest software solves the issues below:

NOTE: Each release contains all solutions identified in the earlier version.

RAM10A 0.9Y *(Date published: 2010-08-26)*

- TV has no picture but sound is available.
- The LED of the TV keeps blinking.

RAM10A 0.9T *(Date published: 2010-05-03)*

- TV switches off by itself during USB playback.
- Picture flicker during playback of 1080P video content from Philips HTS-7200 DVD connected via HDMI.

RAM10A 0.9Q *(Date published: 2010-04-01)*

- Initial production software.