

### **Software History**

**NOTE:** Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

**TPS1011A\_50PFA4509\_V2.01** (*Date published: 2014-04-2*)

Improve AV SECAM picture quality.

**TPS1011A\_50PFA4509\_V2.00** (*Date published: 2014-03-27*)

Initial production software.