

## Software History

### Warning:

This software is only for TV set with TPN149E\_X.XXX.

Always check the current software in your TV set before you update the software. Uploading the wrong software to your TV set may cause malfunction to your TV set.

**NOTE:** Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

#### **TPN149E\_V3.350** (Date published: 2016-04-07)

- Correction of LED standby state
- Solves "INFO" key issue when in EPG

#### **TPN149E\_V3.340** (Date published: 2015-12-03)

- Ability to tune to Turksat and Digiturk (specific to country Turkey only)
- Add new cable operator [Voo] in Belgium

#### **TPN149E\_V3.330** (Date published: 2015-08-27)

- Improve DVB-S channel list issue

#### **TPN149E\_V3.320** (Date published: 2015-07-02)

- Behavior change: Do not output audio without video codec
- Macedonian language not display well in search for channels UI
- Telekabel in MK: TV reboots instead of Stand-by
- TV is switching channels by itself
- [Spain] loss of services from channel grid
- Subtitles were not correctly shown
- Zapping the favorite channel list, no "non-favorite" channels should be encountered

#### **TPN149E\_V3.280** (Date published: 2015-02-17)

- Add Macedonian language and E-DFU.

#### **TPN149E\_V3.270** (Date published: 2014-12-15)

- Fix issue: DVB-S channel sorting / numbering in the favorite list is not working.
- Fix issue: There is gap in channel grid with DVB-C KDG.

#### **TPN149E\_V3.250** (Date published: 2014-11-27)

- Fix issue: KDG- radio channel is lost.
- Fix issue: KDG - reboots during auto scan (410MHz).
- Fix issue: [Switzerland] DVB-C 698MHz reboots during auto scan.
- Fix issue: DVB-S loses channel for Astra.

#### **TPN149E\_V3.240** (Date published: 2014-10-29)

- Fix issue: Long delay when switch between channel RTHD and BBC World.
- Fix issue: Satellite on Unicable bad reception.

- Fix issue: Picture blanked for a while after channel
- To fix channel order issue.
- ARC behavior change in HDMI and PVR source.
- Optimization of backup data base time.
- DVB-S new channel behavior change.

**TPN149E\_V3.230** *(Date published: 2014-09-29)*

- Add Hebrew language.
- Fix issue: Cracks on Nicam during zapping.
- Fix issue: Slovenia "Analogue channels" default set to off.
- Fix issue: Slovenia translation error.
- Fix issue: Power off TV, picture and audio delay about 5s.
- Fix issue: Teletext language group value not able to keep last status.
- Fix issue: Set reboot when press RC power key.
- Fix issue: Set does not find any satellite on Unicable only & channel list available but No Signal.

**TPN149E\_V3.000** *(Date published: 2014-07-28)*

- Add PVR EDFU.

**TPN149E\_V2.100** *(Date published: 2014-07-07)*

- Feature implementation: PVR function.
- Fix issue: TXT improvement.

**TPN149E\_V2.090** *(Date published: 2014-06-13)*

- Fix issue: [Italy] channel loss.
- Fix issue: No translation string "The former channel is moved to".

**TPN149E\_V2.080** *(Date published: 2014-05-23)*

- Cannot reorder DVB-S in favorite list.
- PQ issue on Analogue channels.
- Fix issue: Jumping channels by itself in channel list & favorite list.
- Fix issue: TV lost all digital channels in standby mode.
- Fix issue: [Italy] 191.5MHz and 786MHz channel loss issue.
- Issue fix: [Portugal] DVB-T reboots sporadically.

**TPN149E\_V2.070** *(Date published: 2014-04-23)*

- E-sticker: Add e-sticker icon for extern model.
- Fix issue: Estonia cracking sound issue for ATV.
- Fix issue: Austria UPC jumping channel by itself.

**TPN149E\_V2.060** *(Date published: 2014-04-09)*

- Fix issue: UK channel sorting issue.
- Fix issue: CI CAM pin code message fixed.

**TPN149E\_V2.050** *(Date published: 2014-03-25)*

- Help content not as the same as SPEC

- Fix issue: Search the DVB-C channel in Norway/Belgium by quick/advance scan, TV lost DTV channel.
  - Fix issue: Use Local joystick, cannot switch to Satellite/TV.
  - Fix issue: Bass/Treble values do not be stored after power off/on.
  - Fix issue: Set will reboot after power off about 15min.
  - Fix issue: [UK] in DVB-T full scan finished, ATV source picture format =super zoom then picture shift function icon is display disable.
- 
- Fix issue: Menu language lost Arabic.
  - Fix issue: K-model channel scan issue.
  - Fix issue: change string in SAM mode immediately -> immediately

**TPN149E\_V2.040** (*Date published: 2014-03-17*)

- Fix issue: Character set for Cyrillic.
- Fix issue: Dutch language translation.
- Prevent action: Sync 2K13 set solution of startup reboot issue.
- Prevent action: Sync 2K13 set DVB-T Modena reboot issue when channel scan in Italy.

**TPN149E\_V2.030** (*Date published: 2014-02-27*)

- Default value update: Add Greece/Ireland in H/88 country list.
- Satellite scan mode change: Remove scan mode page for K model.

**TPN149E\_V2.020** (*Date published: 2014-02-21*)

- Default country/language value in UK/English for H/88 model.
- Remove set pin code menu and parental rating Age none in UK.

**TPN149E\_V2.010** (*Date published: 2014-01-24*)

- Initial production software for H & T models.