

Software history – Philips 2K21 85x6/9006/9206/9636/OLED706/OLED8x6/OLED936 ranges

TPM211EA_001.001.233.012– Date: 2021/10/04

- Fixes for HD+ Operator application for Germany
- Fix for colour flashes after start-up from standby
- Improvements for audio loss on TV speaker
- Update for Play-Fi

TPM211EA_001.001.233.005– Date: 2021/09/10

- Support for HD+ Operator application for Germany
- Improvements for start-up issues (no picture after startup)
- Improvements for stability issues (reboots, freezes, black picture)
- Improvements for Picture Quality

TPM211EA_001.001.212.206– Date: 2021/08/20

- SW update for all series
- Fix for no picture on HDMI PS4
- Improvements for audio drops/loss on HDMI, TV speakers
- Improvements for channel management, empty channel list, loss of channels
- Improvements for Picture Quality

TPM211EA_001.001.170.007– Date: 2021/07/16

- Update SW for the 2K21 9206 series

TPM211EA_001.001.170.006– Date: 2021/07/12

- Initial SW for the 2K21 9206 series

TPM211EA_001.001.170.005– Date: 2021/07/08

- Initial SW for the 2K21 77OLED806 and 9636 series

TPM211EA_001.001.170.004– Date: 2021/06/30

- Initial SW for the 2K21 OLED8x6 and 9605 series
- Fix for sound heard from soundbar while TV in standby
- Fix for HBO
- Fix for distorted sound with Dolby Atmos
- Improvement for audio drops/audio loss
- Improvement for DVBS wrong channel list updates
- Improvement for casting
- Improvement for lipsync
- Improvements for stability issues (no startup, reboot, freezes)
- Improvements for TV Guide

TPM211EA_001.001.113.216– Date: 2021/05/12

- Initial SW for the 2K21 OLED706 (excl 70") series

TPM211EA_001.001.113.209– Date: 2021/04/29

- Initial SW for the 2K21 85x6/9006 series