

## Software history

### Philips 2K21 6707/6906/79x6/7406/8106 - ranges

#### TPM215E \_ 001.001.168.014– Date: 2022/4/30

- Improvements on system stability
- Improvements for system speed

#### TPM215E \_ 001.001.168.009/010– Date: 2022/3/31

- Solution for installing apps on 6707 models
- Improvements for Wifi connection
- Improvements for HBO playback

#### TPM215E \_ 001.001.168.002– Date: 2022/1/31

- Improvement for system speed
- Improvement for in app casting ( dedicated apps)
- Improvements in firmware stability
- Improvement for device start up with blanked picture
- Improvement for Wifi connection ( password loss)
- Improvement for hang up during virgin installation
- Solution HDR and DolbyVision notifications

#### TPM215E \_ 001.001.091.006– Date: 2021/12/06

- Solution for dotted lines on picture in Italy
- Solution for wrong audio track in Italian broadcast
- Solution for Dolby Atmos notification in designated app playback
- Improvements for casting difficulties
- Solution for non-picture on 70PUT7906
- Software stability improvements

#### TPM215E \_ 001.001.091.003– Date: 2021/11/01

- Additional screen to inform mandatory firmware upgrade
- Extra feature to disable TV speakers when optical output is used
- Solution for blank screen in 70" panel
- Improved naming for HDMI scaling
- Updated pre-installed app versions
- Firmware stability improvements

#### TPM215E \_ 001.001.028.209– Date: 2021/09/20

- Support for additional panels
- Improvements for light output
- Additional storage warning added
- Correction menu items

#### TPM215E \_ 001.001.028.204– Date: 2021/08/16

- Solution for device hang up after firmware upgrade
- Additional countries in TV installation
- Improvements for retail mode
- Improvements for firmware stability Bluetooth combination
- Initial firmware for the 6906 range
- General performance improvement

#### TPM215E \_ 001.000.200.218– Date: 2021/06/18

- Solution for firmware update progress
- Solution for blanked picture at start-up
- General performance improvement

#### TPM215E \_ 001.000.200.212– Date: 2021/05/27

- Production firmware for the 79x6/7406/8106 range

**TPM215E \_ 001.000.173.208– Date: 2021/03/29**

- Initial firmware for the 79x6/7406/8106 range