

Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPM186E_018.004.189.001 (*Date published: 2019-07-16*)

- To solve set top box remote controls launch to the TV command.

TPM186E_018.004.179.001 (*Date published: 2019-06-24*)

- [Miracast] improved Miracast detected issue when TV turn on.

TPM186E_018.004.136.001 (*Date published: 2019-04-11*)

- [Smart TV] Lack of title when language sets to Bahasa Melayu.

TPM186E_018.004.126.001 (*Date published: 2019-03-18*)

- [Smart TV] connection issue related to iPV6 DNS query.
- [Smart TV] EROSNOW app playback issue.
- [Smart TV] Toggle red button does not appear after changing TV network name.

TPM186E_018.004.083.001 (*Date published: 2018-12-10*)

- Resolve device portal connection issue.
- Resolve the timeshift playback control bar display issue.

TPM186E_018.004.029.001 (*Date published: 2018-10-02*)

- E-sticker update.
- UI update for OLED 873 series.

TPM186E_018.002.251.001 (*Date published: 2018-09-08*)

- Initial production software for AU.

TPM186E_018.002.234.001 (*Date published: 2018-08-29*)

- E-DFU update.

TPM186E_018.002.178.041 (*Date published: 2018-08-10*)

- PQ & AQ setting update.

TPM186E_018.002.178.031 (*Date published: 2018-08-01*)

- Initial production software for AP/MEA.