

Software History

Philips 2K20 82x5/9000/OLED805/OLED935 – ranges

Philips 2K19 7374/OLED804/OLED934 – ranges

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPM191E_101.102.063.000 *(Date published: 2021-06-17)*

- [Mewatch] Red button not appearing after AC power cycle
- After the remote control is turned on, the TV stays at the last power-off source
- Fix TV cannot turn on via remote control
- Fix for no sound after standby
- Stability improvements
- Other general improvements

TPM191E_101.101.250.002 *(Date published: 2021-03-12)*

- [Wifi] connection improve.
- [App_Youtube] fix the screen turns black briefly for one second.
- Fix for no UHD playback in Disney+.
- Fix for subwoofer pre out not working after StandBy.
- Fix for garbage bar on top of screen.
- Fix for unexpected appear of OLED screen server when use apps from Philips TV collection.
- Not responding for Logitech Harmony RC direct commands is fixed.
- Stability improvements.
- Other general improvements.

TPM191E_101.001.145.003 *(Date published: 2020-12-22)*

- [Wifi] support 5G (band 4) WiFi network.
- New item adds in Sound UI: DTS Play-Fi.

TPM191E_101.001.145.001 *(Date published: 2020-11-03)*

- [Wifi] support 802.11r mesh WiFi network.
- [App_Netflix] ATMOS sound quality improve.
- Remove some Ambilight styles in 2k19 range (unification with 2k20 range)

TPM191E_001.004.097.000 *(Date published: 2020-07-21)*

- [Android] System optimization.

Note: This is switch from 2K19 to 2K20 SW version.

TPM191E_001.004.087.000 *(Date published: 2020-05-13)*

- Dolby vision notification=on, but it can't show "Dolby vision".

TPM191E_001.004.052.000 *(Date published: 2020-03-13)*

- [App_iQiY] Lip sync issue.

TPM191E_001.003.200.003 *(Date published: 2020-01-22)*

- Bluetooth remote control software upgrade
- [App_Netflix] Dolby ATMOS & Sunrise function.

TPM191E_001.002.182.001 *(Date published: 2019-12-11)*

- Improvements for Bluetooth remote control pairing.

TPM191E_001.001.114.002 *(Date published: 2019-10-23)*

- [App_Youtube] TV can wake up from standby when cast Youtube.
- TV has no picture with audio output after switch source from HDMI with Dolby vision signal to other source.

TPM191E_001.001.095.001 *(Date published: 2019-09-14)*

- Initial production software.