

Software history

Philips 2K20 75x5/76x5 - ranges

TPN206E _ 203.002.143.031– Date: 2021/04/14

- Solution Rakuten VoD service
- Solution for Poland broadcast issue
- Solution vertical lines during VoD Playback
- Solution vertical lines during HBBTv Playback
- Solution for pink picture while in monitor playback
- General improvements

TPN206E _ 203.002.099.021– Date: 2020/11/13

- Solution for no sound in standby
- Solution audio and video sync TV2 Play app (Denmark)
- Solution for no picture at start-up
- Solution for no sound on Polsat decoder (service contact required)
- Solution for MeGoGo app (DRM security)
- Solution for UHD playback in OKKO app
- Solution for German HBB-TV
- General improvements

TPN206E _ 203.002.076.011– Date: 2020/10/27

- Solution for no sound in standby (Sweden)

TPN206E _ 203.002.076.001– Date: 2020/09/14

- General improvements

TPN206E _ 203.002.063.051– Date: 2020/08/28

- Improvement for connection Prime VoD
- General improvements

TPN206E _ 203.002.063.031– Date: 2020/08/24

- Solution picture scaling issue Ireland

TPN206E _ 203.002.063.011– Date: 2020/08/04

- General improvements

TPN206E _ 203.002.035.071– Date: 2020/07/07

- Solution for audio issue in Nordic VoD services

TPN206E _ 203.002.035.061– Date: 2020/06/22

- General improvements

TPN206E _ 203.002.009.041– Date: 2020/05/07

- Initial firmware for the 2K20 75x5/76x5 ranges