

Software history –

Philips 2K21 85x6/9006/9206/9636/OLED706/OLED8x6/OLED936 ranges

Philips 2K22 8507/88x7/OLED707/OLED807 /PML9507/OLED907/OLED937 ranges

TPM211EA_101.001.003.223– Date: 2022/10/21

- Fix for DVB-S incorrect channel number shown on favourite list
- Fix for DVB-S numeric keys not working in favourite list
- Fix for DVB-C teletext corruption issue
- Fix for picture flicker after rebooting Xbox
- Improvements for HBBTV teletext and audio/video playback issues
- Improvements for Picture Quality
- Improvements for stability issues (reboots, freezes)

TPM211EA_101.001.003.215– Date: 2022/09/16

- Fix for BBC app connection loss
- Fix for A1 Xplore TV app playback failing
- Fix for HBBTV playback failing
- Fix for failing channel recording due to HDD no free space
- Improvements for audio and picture loss on HDMI
- Improvements for Ambilight style parameter loss
- Improvement for audio quality
- Improvement for picture quality
- Improvements for stability issues (reboots, freezes)
- Change for Shop mode, default light sensor setting changed to OFF
- Support for M7 HbbTV OpApp in countries: Netherlands, Belgium, Romania, Czech Rep., Austria, Hungary, Slovakia, Luxembourg

TPM211EA_101.000.178.222– Date: 2022/07/20

- Initial Android R software for 2K22 OLED907/OLED937 series
- Fixes for channel list issues
- Fix for Disney+ subtitle issue
- Fix for start-up with Google Cast
- Fix for excessive EMMC wear specifically for UK
- Improvements for ambilight performance – next generation ambilight
- Improvements for HDMI eARC audio issues
- Improvements for stability issues (reboots, freezes)

TPM211EA_101.000.178.206– Date: 2022/05/20

- Initial Android R software for 2K22 88x7/OLED707/OLED807/PM9507 series
- Fix for Ambilight Hue delay
- Fix for HBBTV audio loss
- Improvements for HDMI eARC audio issues
- Improvements for stability issues (reboots, freezes)

TPM211EA_101.000.136.218– Date: 2022/04/12

- Initial Android R software for 2K22 8507 series
- Software upgrade for the Android Q 2K21 85x6, 9006, 9206 series to Android R

TPM211EA_001.002.114.203– Date: 2022/03/17

- Fix for intermittent loss of AV signal on HDMI source
- Fix for intermittent sound drops via HDMI ARC
- Fix for problems with switch to external audio system
- Fix for no audio and hissing noise via TOSLINK
- Fix for HbbTV not available on DVB-T2 channels
- Fix for pairing issues with Xbox One X controller
- Fix for AL segments don't dim down entirely anymore with black picture content in AL style "game"

TPM211EA_001.001.233.026– Date: 2021/12/14

- Fix for vertical line seen on the right side of the screen eg. OLED screensaver
- Fixes for Calman color calibration functionality
- Improvements for picture quality
 - o Flickering, loss of details, frame drops
 - o shadows around moving objects

TPM211EA_001.001.233.022– Date: 2021/11/29

- Fix for no audio on HDMI eARC
- Fix for audio loss on HDMI eARC
- Fix for auto-wake up due to IR interferences
- Fix for a wrong gradation of the bottom ambient light bar
- Fix for crash in settings menu
- Fix for sound settings not stored or not reset
- Prevention for TV going to factory mode unwanted
- Support for AppleTV pre-installation

TPM211EA_001.001.233.012– Date: 2021/10/04

- Fixes for HD+ Operator application for Germany
- Fix for colour flashes after start-up from standby
- Improvements for audio loss on TV speaker
- Update for Play-Fi

TPM211EA_001.001.233.005– Date: 2021/09/10

- Support for HD+ Operator application for Germany
- Improvements for start-up issues (no picture after startup)
- Improvements for stability issues (reboots, freezes, black picture)
- Improvements for Picture Quality

TPM211EA_001.001.212.206– Date: 2021/08/20

- SW update for all series
- Fix for no picture on HDMI PS4
- Improvements for audio drops/loss on HDMI, TV speakers
- Improvements for channel management, empty channel list, loss of channels
- Improvements for Picture Quality

TPM211EA_001.001.170.007– Date: 2021/07/16

- Update SW for the 2K21 9206 series

TPM211EA_001.001.170.006– Date: 2021/07/12

- Initial SW for the 2K21 9206 series

TPM211EA_001.001.170.005– Date: 2021/07/08

- Initial SW for the 2K21 77OLED806 and 9636 series

TPM211EA_001.001.170.004– Date: 2021/06/30

- Initial SW for the 2K21 OLED8x6 and 9605 series
- Fix for sound heard from soundbar while TV in standby
- Fix for HBO
- Fix for distorted sound with Dolby Atmos
- Improvement for audio drops/audio loss
- Improvement for DVBS wrong channel list updates
- Improvement for casting
- Improvement for lipsync
- Improvements for stability issues (no startup, reboot, freezes)

- Improvements for TV Guide

TPM211EA_001.001.113.216– Date: 2021/05/12

- Initial SW for the 2K21 OLED706 (excl 70") series

TPM211EA_001.001.113.209– Date: 2021/04/29

- Initial SW for the 2K21 85x6/9006 series