

## **Software history (AZ390/12 and AZ390/94)**

**The latest software improves the below:**

**NOTE:** Each release contains all solutions identified in the earlier version.

### **Version 8**

- Solve the issue where the device is automatically powered off after 15 minutes of AUX mode operation.