

Software history BDP2305/05/F7/F8 X/77/12:BDP2300/12

The latest software improves the below:

NOTE: Each release contains all solutions identified in the earlier version.

Version 1.31(for BDP2305/05/F7/F8 X/77/12:BDP2300/12)

- New feature of clearing cookies when there is YouTube playback problem. To do this, follow the steps below:
 - 1) Press [HOME] on the remote control to enter home menu.
 - 2) Within 6 seconds, press [8], [5], [2], [0] buttons on the remote control.

Version 1.29(for BDP2305/05/12/F8/X/77)

- Improve disc playback performance

Version 1.21(for BDP2305/F7/F8 X/77/12:BDP2300/12)

- Improve Wi-Fi connection

Version 1.07(for BDP2305/F7/F8 X/77/12:BDP2300/12)

- Required version for upgrading to v1.21 or above

Version 1.03 (For BDP2300/12; BDP2305/12)

- Improve DVD discs playability performance.