

Firmware history of BM50/10

NOTE: Each release contains all solutions identified in the earlier version.

MCU v082; Wi-Fi FW v0204

- General bug fixes
- Enabled device to play CD layer of SACD (for hybrid two-layer SACD with a CD-compatible second layer)
- Enhanced Bluetooth connection and user interface

MCU v079; Wi-Fi FW v1231

- General bug fixes
- Added remote control LED indication – When signal from the remote control is received, the LED indication flashes.
- Multi-pair performance improvements
- Enhanced Izzylink connection among speakers