

Software history (BTB3370/12)

The latest software solves the issues below:

NOTE: Each release contains all solutions identified in the earlier version.

Version 27:

- Solve the issue about gap between tracks during CD playback.

Version 25:

- Fixed Standby issue with switching source.