

## **Software history (BTM2360)**

The latest software solves the issues below:

NOTE: Each release contains all solutions identified in the earlier version.

Version 32 (BTM2360/12/61/55/96/85/77)

- Solve the issue about gap between tracks during CD playback.

Version 30 (BTM2360/12, /61, /55, /77)

- Solve problem with CD playback