

## **Software history (CSS5123)**

**The latest software solves the issues below:**

**NOTE:** Each release contains all solutions identified in the earlier version.

### **Version V27**

- Improved system performance

### **Version V25**

- Improved compatibility with Telekom Speedport W 920V
- Improved system performance