

## Software history\_CSS5530B/12, /37, CSS5530G/12, /96, CSS5330G/12, CSS5330B/12

**Note: The filename of the bin file may NOT necessary be the same as the model number.**

The latest software solves the issues below:

### Version 35

Local Display version info:

#### CSS5530

- 1) Main Version: **V35**
- 2) Repeater version: **V09**
- 3) TX version: **V09**
- 4) RX version: **V09**

#### CSS5330

- 1) Main Version: **V35**
- 2) Repeater version: **V09**
- 3) TX version: **V04**
- 4) RX version: **V05**

- Added USB (MP3) Playback function
  - For customers using RC without USB playback specific keys, please refer to Philips Support site ([www.philips.com/support](http://www.philips.com/support)) for updated User Manual for instructions to use this feature
- System performance fixes
- Improved startup time when wake up via TV remote control
- Fixed start up issues when wake up via TV remote control
- Fixed test tone in surround sound set up.