

Software history (DTD3190)

Note:

- Each release contains all solutions identified in the earlier version.
 - The filename of the upgrade file is a .bin file. The filename may NOT necessary be the same as the model number.
-

The latest software solves the issues below:

MCU version: v32

- Enhance the equalizer settings.
- Avoid the interference from other Philips remote controls.