

Software history(HTB3510,3510X,3540,3570,3571)

Note:

- The filename of the bin file may NOT necessarily be the same as the model number.
- Each release contains all solutions identified in the earlier version.
- After updating the device, some settings such as HDMI-CEC might be erased. Refer to the user manual for the set-up after updating the device.

The latest software solves the issues below:

Version: v1.29.01(not for /93models)

- Fix MP4 cannot playback via DLNA
- Fix keyboard display error under different languages.

Version:v1.29.00

- Fix bug during start up

Versionv1.28.01(notfor /93models)

- Smart TV update.
- Sound output optimization.
- RDS info display error fix.

Versionv1.26.03

- Enhance playability of MP3 files
- Enhance playability of Blu-ray discs
- Improve performance related to Wi-Fi
- Fix bug related to speaker setup
- Fix bug related to ID3 display in Russian for MP3 files
- Fix bug related to subwoofer
- Fix bug related to bass
- Fix bug related to Russian on-screen display
- Import Smart TV 2.0

Versionv1.26.02(notfor /55,/78,/93,/94models)

- Enhance playability of MP3 files
- Enhance playability of Blu-ray discs
- Improve performance related to Wi-Fi
- Fix bug related to speaker setup
- Fix bug related to ID3 display in Russian for MP3 files
- Fix bug related to subwoofer
- Fix bug related to bass
- Fix bug related to Russian on-screen display
- Import Smart TV 2.0

VersionV1.24.00

- Fix bugs related to HDMI ARC.

VersionV1.23.01(for HTB3510/12,3540/12,3570/12only)

- Fix bugs related to YouTube.

Note: After upgrading with the latest firmware, disconnect the device from power supply. Wait for a few seconds and then reconnect to power supply.