

Software History (HTB5544D/F7)

The latest software improves the below:

NOTE: Each release contains all solutions identified in the earlier version.

Note:

The filename of the bin file may NOT necessary be the same as the model number.

System software version: v1.17.00

- In Compliance with new AACCS specification, Blu-ray playback via CVBS output is now disabled. Please watch your Blu-ray movies via HDMI connection.
- Sound output optimization

System software version: v1.12.03

- Fix bug related to speaker setup
- Improve Lip sync performance
- Enhance playability of MP3 files
- Improve Wi-Fi performance quality
- Enhance playability of Blu-ray disc