

Software history (HTS3541/05, /12, /51, /55, /78, /79, /93, /98)

The latest software solves the issues below:

NOTE: Each release contains all solutions identified in the earlier version.

Version V1.56.10

(Important note: This version is applicable ONLY to products that has the serial number starting with "KX1A".)

- Improved system performance

Version V1.52.00

(Important note: This version is applicable ONLY to products that has the serial number starting with "KX1A".)

- Introduction of Youtube/Picasa features
- Improved system performance

Version V1.41.00

- Solved the Audio Sync Adjustment issue
- Improved system performance

Version V1.38.10

- Solved the Audio Sync Adjustment issue
- Improved system performance

Version V1.32, Subsystem V18

- Improved system performance